



30 minute cure time

Benefits

- Kitted system containing all components
- Ideal for improving efficiency
- Quick cure time
- Unique pre-measured resin bag guarantees correct mix
- Lowers cost of labor
- Trenchless point repair technology

Technical Specifications

- At 68°F, the working time is 6-7 minutes, with a cure time of approximately 30 minutes
- Lower temperatures extend working and cure time
- Higher temperatures reduce working and cure time
- The working and cure time starts when the resin is mixed